

- ① SR50AH v.s. SR50A-316SS for marine use
- ② order 19517 mounting kit 1"-1.75" pipe (see #7)
- ③ integrated Temperature? or add later SR50AH v.s. SR50
- ④ set jumpers for proper data format and in RUN position ^{ATH}
- ⑤ Viewing Radius = $0.268 * H$ $H = \text{mesh to surface} (\sim 30^\circ)$
- ⑥ Δd 8.00mm + mesh to lip
- ⑦ or order 19484 mounting stem with NU-Rail Fitting (17953)
- ⑧ Temperature Compensation Distance = Reading $\sqrt{\frac{T^\circ \text{Kelvin}}{273.15}}$
- ⑨ check Vent Holes and Desiccant
- ⑩ Heater must BE OFF for temps $> 25^\circ\text{C}$

<https://www.roxtec.com/en/products>

Contact

Roxtec International AB

Box 540

371 23 Karlskrona

Sweden

Phone: +46 455 36 67 00

Fax: +46 455 820 12

Email: info@roxtec.com

Visiting address:

Rombvägen 2

371 65 Lyckeby

Sweden

Product model HD 32/32 Ex